

Document information


This document lists the new features and bugfixes available in the new GigaCore firmware.

1. Added support for the new RPSU 400



More information regarding the functionality and specifications of the RPSU 400 can be found [here](#).

2. Added option to disable tag native VLAN on ISL



This menu offers the user to connect third party network device who cannot communicate with the switch through tagged management packets.